



## Model 199116-7 Parts List

A = Standard Equipment

O = Circuit Diagram

Item#	Part#	Description	Q'ty Unit
1	161646-8	SIDE GUARD	2 PC.
2	457744-7	CAP 22	6 PC.
3	251541-1	THUMB SCREW M8X25	4 PC.
4	457743-9	CAP 30	4 PC.
5	265846-3	H.S.SET SCREW(CUP POINT)M8X16	2 PC.
6	161645-0	FRONT GUARD	1 PC.
7	934401-9	WING NUT M8	4 PC.
8	942201-3	SPRING WASHER 8	4 PC.
9	941201-0	FLAT WASHER 8	4 PC.
10	941201-0	FLAT WASHER 8	2 PC.
11	921497-9	HEX.BOLT M8X75	2 PC.
12	161644-2	BASE	1 PC.
13	941201-0	FLAT WASHER 8	2 PC.
14	921472-5	HEX. BOLT M8X50	2 PC.