



Model WT03Z Parts List

A = Standard Equipment

O = Circuit Diagram

Item#	Part#	Description	Q'ty Unit
001	183J75-5	HOUSING SET	1 PC.
	C10 252126-6	HEX. LOCKING NUT M4-7	2 PC.
	D10	INC. 27	
002	266429-2	TAPPING SCREW 3X16	8 PC.
003	456039-5	F/R CHANGE LEVER	1 PC.
004	632M06-4	SWITCH UNIT	1 PC.
	D10	INC. 29	
005	422407-4	BUMPER	1 PC.
006	323675-1	PIN 4	1 PC.
007	140D36-2	HAMMER CASE COMPLETE	1
	C10 213882-3	O-RING 16	1 PC.
008	261140-1	NYLON WASHER 20	1 PC.
009	322045-1	CLIP	1 PC.
010	136089-3	ANVIL A ASS'Y	1
	D10	INC. 6,9	
011	327334-9	HAMMER	1
012	216019-1	STEEL BALL 3	24 PC.
013	267380-9	FLAT WASHER 20	1 PC.
014	232517-7	COMPRESSION SPRING 21	1
015	267813-4	WASHER 21	1 PC.
016	216002-8	STEEL BALL 4.8	2 PC.
017	226190-3	SPUR GEAR 18	2 PC.
018	327127-4	SPINDLE	1 PC.
019	268217-3	PIN 3.5	2 PC.
020	253052-2	FLAT WASHER 12	1 PC.
021	226957-9	INTERNAL GEAR 45	1 PC.
022	140P27-5	BEARING BOX COMPLETE	1 PC.
	C10 213188-9	O-RING 13	1 PC.
023	632L96-1	MOTOR COMPLETE	1 PC.
024	422273-9	CUSHION	4 PC.
025	644813-5	TERMINAL	1 PC.
026	855S56-0	WT03 SERIAL NO. LABEL	1
027	183J75-5	HOUSING SET	1 PC.
	C10 252126-6	HEX. LOCKING NUT M4-7	2 PC.
	D10	INC. 1	
028	855S49-7	WT03 NAME PLATE	1
029	620625-0	LED CIRCUIT	1 PC.
030	819M49-5	CAUTION LABEL	1
	213458-6	O RING 34	1
A01	266622-8	+ TRUSS HEAD SCREW M4X12	1 PC.
A02	346909-5	HOOK	1 PC.